Colorada rogram

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name:

Work Order Type: Weatherization Audit Name: MCNAIRY

CLIENT INFORMATION

Client Name:

Address:

Client ID:

Alt. Client ID: 16016SW-0915

AGENCY INFORMATION

Agency: SWHRA

Agency Phone: (731) 989-5111

Address: 1574 White AVE

Fax:

Henderson, TN

Email Address:

Agency Contact: Murley, Rickey

Work Phone: Cell Phone: Email Address:

Company Name & License Num	ber:
Contractor's Signature:	

COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-632-1484

Client Name:

Work Order (Bid Form)

DOE Weatherization Assistant

Client ID:

Work Order Name:

Version 8.5.0 Report Run On: 5/23/2010

Page 1 of 6

Alt. Client ID: 16016SW-0915

Measures

i	Measure 1 Infilt	ration Redctn			Componen	ts		I	nspected
C	omment								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Seal around breaker box,Seal pipes under vanity and crown molding in Kitchen, Seal pipes under kitchen sink and bathroom door jam	Each	1					
2	Labor	Labor	Hour						
3	Construction Materials/Hardwar e	Caulk inside and out all windows	Each	1					
4	Labor	Labor	Hour						
2	other Detail								
					and the second s			A Property of the Control of the Con	
Γ					100000000000000000000000000000000000000				
				Measur	e Sub Total:			Sub Total:	
Terretorial bereist trappet siretaiste imbelle et secretorial servicator	Field Notes:								

Measure 2 DW	H Pipe Insulation			Componen	ts		I	nspected
Comment								
				Estimated	!		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	Labor	Each	1		America Control of the Control of th			
Other Detail			,			¬		
			Measur	e Sub Total:] ,	Sub Total:	
Field Notes:								
Measure 3 Atti	c Ins. R-30			Componen	ts A1		1.	nspected
C								
Comment								
Comment				Estimated	!		Actual	
# Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
	Attic Insulation - Blown	<i>Units</i> SqFt	Qty 512			Qty		Total
# Material / Labor			_			Qty		Total
# Material / Labor	Attic Insulation - Blown		_			Qty		Total
# Material / Labor 1 Insulation 2 Labor	Attic Insulation - Blown Cellulose - R-30	SqFt	512			Qty		Total
# <i>Material / Labor</i> 1 Insulation	Attic Insulation - Blown Cellulose - R-30	SqFt	512			Qty		Total
# Material / Labor 1 Insulation 2 Labor	Attic Insulation - Blown Cellulose - R-30	SqFt	512			Qty		Total
# Material / Labor 1 Insulation 2 Labor	Attic Insulation - Blown Cellulose - R-30	SqFt Each	512					Total
# Material / Labor 1 Insulation 2 Labor Other Detail	Attic Insulation - Blown Cellulose - R-30	SqFt Each	512	Unit Cost			Unit Cost	Total
# Material / Labor 1 Insulation 2 Labor	Attic Insulation - Blown Cellulose - R-30	SqFt Each	512	Unit Cost			Unit Cost	Total
# Material / Labor 1 Insulation 2 Labor Other Detail	Attic Insulation - Blown Cellulose - R-30	SqFt Each	512	Unit Cost			Unit Cost	Total

Page 3 of 6

Measure 4 Stor	m Windows			Componen	ts N1		ı	nspected
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Storm Window	Each	1					
2 Labor	Labor	Hour						
Other Detail				1				
			Measur	e Sub Total:] .	Sub Total:	
Measure 5 CO	Monitor is Needed	. Ho. A.		Componen	!s			Inspected
Comment				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	CO monitor	Each	1					
2 Labor	Labor	Hour	1					
Other Detail			ſ					

			Measur	e Sub Total:]	Sub Total:	
Field Notes:		4 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2				4		

Measure 6 FIX F	Any Other Heating Syste	em Proble	em	Component	ts		L	nspecte
omment Remove	non-vented heaters that	do no ha	ve a o	xygen deple	tion sens	or		
				Estimated			Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	Direct Vent 20-25 KBTU Propane Heater	Each	1					
Labor	Labor	Hour	1					
Other Detail						1		
			Measur	e Sub Total:] ;	Sub Total:	
Measure 7 Fix C	Other Water Heating Pro	oblem		Componen	ts		I	nspecto
				م بید			4 4 !	
Material / Labor				Estimated			Actual	
Hamilton and Cafatu	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
Items	-	<i>Units</i> Each	Qty 1		Total	Qty		Total
Items	Repair electrical connection on water		_		Total	Qty		Total
Items	Repair electrical connection on water heater	Each	1		Total	Qty		Total
Items	Repair electrical connection on water heater	Each	1		Total	Qty		Total
Items	Repair electrical connection on water heater	Each	1		Total	Qty		Total
Health and Safety Items Labor Other Detail	Repair electrical connection on water heater	Each Hour	1		Total			Total

Client Name: Client ID:

Alt. Client ID: 16016SW-0915

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/23/2010

DOE Weatherization Assistant Version 8.5.0

Page 5 of 6

Measure 8 Smo	ke Detector is Needed			Componen	ts		I	nspected
Comment								
				Estimated	!		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	Smoke detector	Each	1				The state of the s	
2 Labor	Labor	Hour	1					
Other Detail			Measur	e Sub Total:			Sub Total:	
Field Notes:								
	To an analysis of the second s	Work Or	der Gra	nd Total:		Gran	d Total:	

Report Run On: 5/23/2010

Page 6 of 6